



Model: Tacho Sensor

- Be used for gear rotation speed measurement
- Combining the advantages of stable signal, wide range of operating temperature, smallsize, simple assembly, etc
- It covers a wide range of measurement, and it is able to measure the zero rotation speed
- The shell appearance, material and thread fitting can be customized as requires
- ◆ Operating voltage: 8~32Vwith polarity protection
- ◆ Operating current: <50mA</p>
- Operating temperature:-40 ~150℃
- ◆ Output signal:Square wave or sine wave
- ◆ Signal duty factor: 47±5%
- ◆ Inductance distance:0.5~2.5mm
- ◆ Tooth module: 2~6
- ◆ Thread fitting:UNF5/8 or M16
- . Connecting way: two wires or three wires connecting
- ◆ Protection rank:IP67